



Part No: 530221

UHF HANDPIECE/MICROPHONE BRACKET TO  
SUIT TOYOTA HILUX (LATE 2015-APRIL 2020)  
(530221)-530221

ACCESSORY PART NO: 530221

Installation Time: 10 min

**Care Instructions:**

Clean item with mild detergent and water solution.  
Do not use abrasive cleaners

**Warnings:**

Please check all parts are complete according to the parts list prior to installation of the product. If parts are missing, please contact us as attempting to install an incomplete kit may void your warranty. We highly recommend that this product is installed by a professional fitter. Bosscoauto is not liable for damage to the vehicle or product due to installation error.



**Recommended fitters:**

Scan the following QR code to find our network of recommended fitters all over Australia. Book can do the hard work for you!

Disclaimer: These are all separate businesses to Bossco4x4 and we are not liable for their work






Part No: 530221

**Parts List**

Item	Part Name	Qty
1	UHF Bracket	1
2	M3x16mm bolt	2
3	M3 Nut	2
4	Alcohol Pad	1
5	Adhesion promoter	1
6	Instructions	1





Part No: 530221

### Step 1

Attach the microphone mount supplied by your UHF Radio manufacture to the bracket.



### Step 2

Wipe the area where the bracket is to be installed thoroughly with the supplied alcohol wipe.

### Step 3

We recommend doing a test fitting before removing the backing paper from the double sided tape.

Place the bottom face of the bracket, flush with the left bottom corner of the radio and the rotate the bracket slightly outwards, slide the bracket inside the gap between the radio and the dash, making sure the double side tape does not touch edges of the radio, then gently lock the bracket into place, apply firm pressure to the bracket for at least 20 seconds.

IMPORTANT: DO NOT HANG THE HANDPIECE/MICROPHONE FOR AT LEAST 72 HOURS

